


Design-Build-Commissioning Study - Army

System Condition Index (SCI) by System

For NG Armed Forces Reserve Center, Sand Springs, OK (104B)



<i>Inspected Systems</i>	<i>SCI</i>
Conveying	98
Electrical	99
Exterior Circulation	91
Exterior Closure	93
Fire Suppression	99
HVAC	99
Interior Construction	94
Plumbing	98
Roofing	79
Specialties	98
Structural	95